

## **Rural Municipality of East St. Paul Bottomley Creek Bank Remediation and Permanent Dike Construction Update - September 10th to September 23rd, 2017**

### Work Performed:

- Foundation for house side segmental block wall at 3144 Henderson Highway was completed, segmental block wall placement began.
- Lower terrace segmental block wall on the house side of the new dike was placed at 1030 Highland Park Drive.
- Upper terrace segmental block wall on the house side of the new dike was placed at 1020 Highland Park Drive.
- Stair construction on the house side segmental block wall began at 1030 Highland Park Drive and 3144 Henderson Highway.

### Photographs:



**Photo 1 - Stair construction at 3144 Henderson Highway.**



**Photo 2 - House side segmental block wall placement at 3144 Henderson Highway.**



**Photo 3 - House side segmental block wall placement at 3144 Henderson Highway.**



Photo 4 - House side segmental block wall placement at 3144 Henderson Highway.



Photo 5 - Stair location on lower terrace segmental block wall at 1020 Highland Park Drive.



**Photo 6 - Upper terrace house side segmental block wall placed at 1020 Highland Park Drive.**



**Photo 7 - House side segmental block wall placement at 3144 Henderson Highway.**



**Photo 8 - House side segmental block wall placement at 3144 Henderson Highway.**