

Rural Municipality of East St. Paul Bottomley Creek Bank Remediation and Permanent Dike Construction Update - February 19th to February 25th, 2017

Work Performed:

- Due to warm weather and rain over the long weekend, the water level in the Bottomley Creek increased approximately 1 m. No work was completed this week to allow the water level to decrease and refreeze.

Photographs:



Photo 1 - Increased water level at 1020 Highland Park Drive and 3144 Henderson Highway.



Photo 2 - Increased water level at 1030 Highland Park Drive.



Photo 3 - Increased water level at Tartan Way culvert.



Photo 4 - Increased water level at 1040 Highland Park Drive and 3154 Henderson Highway.