

Rural Municipality of East St. Paul Bottomley Creek Bank Remediation and Permanent Dike Construction Update - March 12th to March 18th, 2017

Work Performed:

- Placement and shaping of the rockfill toe berm at 1020, 1030 & 1040 Highland Park Drive and 3144 & 3154 Henderson Highway.
- Removed cofferdam at the north end of the creek.
- Topsoil to be placed on top of the rockfill toe berm was hauled to 3154 Henderson.

Photographs:



Photo 1 - Hauling rockfill for toe berm at 1040 Highland Park Drive.



Photo 2 - Shaped rockfill toe berm at 1030 Highland Park Drive and placed rockfill at 3144 Henderson Highway.



Photo 3 - Shaped rockfill toe berm at 3154 Henderson Highway.



Photo 4 - Cofferdam removed between 1040 Highland Park Drive and 3154 Henderson Highway.



Photo 5 - Rockfill toe berm placement at 1020 Highland Park Drive.



Photo 6 - Topsoil starting to get hauled to 3154 Henderson Highway.