

## Rural Municipality of East St. Paul Bottomley Creek Bank Remediation and Permanent Dike Construction Update - August 27th to September 2nd, 2017

### Work Performed:

- Foundation for house side segmental block wall at 1020 and a portion of 1030 Highland Park Drive was completed.
- Tree wells completed at 3154 Henderson Highway.
- Clay fill was placed for new dike at 3154 Henderson Highway.
- Native Plant Solutions planted remainder of trees and shrubs required on rockfill toe berm.

### Photographs:



**Photo 1 - Foundation for house side segmental block wall at 1020 Highland Park Drive.**



**Photo 2 - Foundation for house side segmental block wall at 1030 Highland Park Drive.**



**Photo 3 - New trees and shrubs planted on rockfill toe berm.**



Photo 4 - New tree planted on rockfill toe berm.



**Photo 5 - New trees and shrubs planted on rockfill toe berm.**



**Photo 6 - Placement of clay fill for new dike and rock for tree wells at 3154 Henderson Highway.**



Photo 7 - Tree well at 3154 Henderson Highway.



**Photo 8 - Placement of clay fill for new dike side slope at 3154 Henderson Highway.**