

## Rural Municipality of East St. Paul Bottomley Creek Bank Remediation and Permanent Dike Construction Update - September 3rd to September 9th, 2017

### Work Performed:

- Foundation for house side segmental block wall at 3144 Henderson Highway was excavated and partially filled with gravel.
- Lower terrace segmental block wall on the house side of the new dike was placed at 1020 Highland Park Drive.
- Segmental blocks placed around the tree at 1020 Highland Park Drive to replace original segmental block wall that was removed.
- Stair construction on the lower terrace segmental block wall began at 1020 Highland Park Drive.

### Photographs:



**Photo 1 - Foundation for house side segmental block wall at 3144 Henderson Highway.**



**Photo 2 - Foundation for house side segmental block wall at 3144 Henderson Highway.**



**Photo 3 - Foundation for house side segmental block wall at 3144 Henderson Highway.**



**Photo 4 - Lower terrace segmental block wall placed on house side of the new dike and blocks placed around the tree at 1020 Highland Park Drive.**



**Photo 5 - Stair location on lower terrace segmental block wall at 1020 Highland Park Drive.**