

Rural Municipality of East St. Paul Bottomley Creek Bank Remediation and Permanent Dike Construction Update - February 5th to February 11th, 2017

Work Performed:

- Tree pruning/clearing on Bottomley Creek banks at 1020 & 1030 Highland Park Drive and 3144 Henderson Highway.
- Shear key excavation in creek at 1040 Highland Park Drive and 3154 Henderson Highway.
- Rockfill placement in shear keys at 1040 Highland Park Drive and 3154 Henderson Highway.

Photographs:



Photo 1 - Tree clearing at 1030 Highland Park Drive.



Photo 2 - Tree pruning/clearing at 3144 Henderson Highway.



Photo 3 - Tree pruning/clearing at 1020 Highland Park Drive.



Photo 4 - Shear key excavation at 1040 Highland Park Drive and 3154 Henderson Highway.



Photo 5 - Shear key rockfill placement at 1040 Highland Park Drive and 3154 Henderson Highway.