

Rural Municipality of East St. Paul Bottomley Creek Bank Remediation and Permanent Dike Construction Update - August 20th to August 26th, 2017

Work Performed:

- Creek side segmental block wall placement continued at 1020 and 1030 Highland Park Drive.
- Flap gates and canal gates have been placed on all culverts at 1020 and 1030 Highland Park Drive.
- Terraced segmental block wall placement at 1040 Highland Park Drive began.
- Perforated toe and heel drains are completed on creek side segmental block wall at 1020 and 1030 Highland Park Drive.
- Stair placement in the creek side segmental block wall began at 3154 Henderson Highway.
- Capstone placement began for the creek side segmental block wall at 3144 and 3154 Henderson Highway.

Photographs:



Photo 1 - Start of stair placement in creek side segmental block wall at 3154 Henderson Highway.



Photo 2 - Placement of toe and heel drains behind creek side segmental block wall at 1020 Highland Park Drive.



Photo 3 - Placement of toe and heel drains behind creek side segmental block wall at 1030 Highland Park Drive.



Photo 4 - Placement of terraced segmental block wall at 1040 Highland Park Drive.



Photo 5 - Placement of terraced segmental block wall at 1040 Highland Park Drive.



Photo 6 - Capstones placed on creek side segmental block wall at 3144 Henderson Highway.



Photo 7 - Capstones placed on creek side segmental block wall at 3144 Henderson Highway.



Photo 8 - Capstones placed on creek side segmental block wall at 3154 Henderson Highway.