

Rural Municipality of East St. Paul Bottomley Creek Bank Remediation and Permanent Dike Construction Update - March 5th to March 11th, 2017

Work Performed:

- Completed gabion baskets at 1030 Highland Park Drive.
- Placed rockfill toe berm at 1040 Highland Park Drive, 3154 Henderson Highway and 3144 Henderson Highway.
- Pumping of water from Bottomley Creek over cofferdam 24 hours/day, 7 days/week.

Photographs:



Photo 1 - Filling gabion baskets at 1030 Highland Park Drive.



Photo 2 - Installing gabion baskets at 1030 Highland Park Drive.



Photo 3 - Filling gabion baskets at 1030 Highland Park Drive.



Photo 4 - Rockfill toe berm placement at 3144 Henderson Highway.



Photo 5 - Installing culvert through gabion baskets at 1030 Highland Park Drive.



Photo 6 - Completed gabion baskets at 1030 Highland Park Drive.